Montana Board of Oil and Gas Conservation Environmental Assessment

Operator: Whiting Oil and Gas Corporation Well Name/Number:Jacobsen 21-2TFH Location: NE NW Lot 3 Section 2 T29N R57E County: Roosevelt _, MT; Field (or Wildcat) W/C (Three Forks Horizontal)
Air Quality
(possible concerns)
Long drilling time: No, 30 to 40 days drilling time.
Unusually deep drilling (high horsepower rig): No, triple derrick drilling rig to drill a single
lateral Three Forks Formation well test to 19,548'MD/10,168'TVD. Possible H2S gas production: H2S gas production possibility is slight.
In/near Class I air quality area: No Class I air quality area nearby.
Air quality permit for flaring/venting (if productive): Yes, DEQ air quality permit required
under rule 75-2-211.
Mitigation:
_X Air quality permit (AQB review)
Gas plants/pipelines available for sour gas
Special equipment/procedures requirements
Other:
Comments: No special concerns – using triple derrick drilling rig to drill a single lateral Three Forks Formation well, 19,548'MD/10,168'TVD. If existing
pipeline for H2S gas in the area gas can be gathered or if no gathering system
nearby H2S gas can be flared under Board Rule 36.22.1220.
Water Quality
(possible concerns)
Salt/oil based mud: Yes, oil based invert drilling fluids will be used on the mainhole.
The horizontal lateral will be drilled with brine water. The surface hole will be drilled with
freshwater and freshwater drilling fluids
High water table: No, no high water table anticipated in the area of review.
High water table: No, no high water table anticipated in the area of review. Surface drainage leads to live water: No, nearest drainage is an unnamed ephemeral
High water table: No, no high water table anticipated in the area of review. Surface drainage leads to live water: No, nearest drainage is an unnamed ephemeral drainage a pothole lake, about 1/2 of a mile to the northeast from this location.
High water table: No, no high water table anticipated in the area of review. Surface drainage leads to live water: No, nearest drainage is an unnamed ephemeral drainage a pothole lake, about 1/2 of a mile to the northeast from this location. Water well contamination: None, closest water wells are about 5/8 of a mile to the
High water table: No, no high water table anticipated in the area of review. Surface drainage leads to live water: No, nearest drainage is an unnamed ephemeral drainage a pothole lake, about 1/2 of a mile to the northeast from this location. Water well contamination: None, closest water wells are about 5/8 of a mile to the southeast and 3/4 of a mile to the southeast from this location. Depth of these domestic
High water table: No, no high water table anticipated in the area of review. Surface drainage leads to live water: No, nearest drainage is an unnamed ephemeral drainage a pothole lake, about 1/2 of a mile to the northeast from this location. Water well contamination: None, closest water wells are about 5/8 of a mile to the southeast and 3/4 of a mile to the southeast from this location. Depth of these domestic water wells are from 160' to 210'. Surface casing hole will be drilled with freshwater and
High water table: No, no high water table anticipated in the area of review. Surface drainage leads to live water: No, nearest drainage is an unnamed ephemeral drainage a pothole lake, about 1/2 of a mile to the northeast from this location. Water well contamination: None, closest water wells are about 5/8 of a mile to the southeast and 3/4 of a mile to the southeast from this location. Depth of these domestic water wells are from 160' to 210'. Surface casing hole will be drilled with freshwater and freshwater drilling fluids. Surface casing will be run and cemented to surface from 2000'. Porous/permeable soils: No, sandy clay soils.
High water table: No, no high water table anticipated in the area of review. Surface drainage leads to live water: No, nearest drainage is an unnamed ephemeral drainage a pothole lake, about 1/2 of a mile to the northeast from this location. Water well contamination: None, closest water wells are about 5/8 of a mile to the southeast and 3/4 of a mile to the southeast from this location. Depth of these domestic water wells are from 160' to 210'. Surface casing hole will be drilled with freshwater and freshwater drilling fluids. Surface casing will be run and cemented to surface from 2000'. Porous/permeable soils: No, sandy clay soils. Class I stream drainage: No class I stream drainages in this area.
High water table: No, no high water table anticipated in the area of review. Surface drainage leads to live water: No, nearest drainage is an unnamed ephemeral drainage a pothole lake, about 1/2 of a mile to the northeast from this location. Water well contamination: None, closest water wells are about 5/8 of a mile to the southeast and ¾ of a mile to the southeast from this location. Depth of these domestic water wells are from 160' to 210'. Surface casing hole will be drilled with freshwater and freshwater drilling fluids. Surface casing will be run and cemented to surface from 2000'. Porous/permeable soils: No, sandy clay soils. Class I stream drainage: No class I stream drainages in this area. Mitigation:
High water table: No, no high water table anticipated in the area of review. Surface drainage leads to live water: No, nearest drainage is an unnamed ephemeral drainage a pothole lake, about 1/2 of a mile to the northeast from this location. Water well contamination: None, closest water wells are about 5/8 of a mile to the southeast and 3/4 of a mile to the southeast from this location. Depth of these domestic water wells are from 160' to 210'. Surface casing hole will be drilled with freshwater and freshwater drilling fluids. Surface casing will be run and cemented to surface from 2000'. Porous/permeable soils: No, sandy clay soils. Class I stream drainage: No class I stream drainages in this area. Mitigation: X Lined reserve pit
High water table: No, no high water table anticipated in the area of review. Surface drainage leads to live water: No, nearest drainage is an unnamed ephemeral drainage a pothole lake, about 1/2 of a mile to the northeast from this location. Water well contamination: None, closest water wells are about 5/8 of a mile to the southeast and 3/4 of a mile to the southeast from this location. Depth of these domestic water wells are from 160' to 210'. Surface casing hole will be drilled with freshwater and freshwater drilling fluids. Surface casing will be run and cemented to surface from 2000'. Porous/permeable soils: No, sandy clay soils. Class I stream drainage: No class I stream drainages in this area. Mitigation: X Lined reserve pit X Adequate surface casing
High water table: No, no high water table anticipated in the area of review. Surface drainage leads to live water: No, nearest drainage is an unnamed ephemeral drainage a pothole lake, about 1/2 of a mile to the northeast from this location. Water well contamination: None, closest water wells are about 5/8 of a mile to the southeast and 3/4 of a mile to the southeast from this location. Depth of these domestic water wells are from 160' to 210'. Surface casing hole will be drilled with freshwater and freshwater drilling fluids. Surface casing will be run and cemented to surface from 2000'. Porous/permeable soils: No, sandy clay soils. Class I stream drainage: No class I stream drainages in this area. Mitigation: X Lined reserve pit X Adequate surface casing Berms/dykes, re-routed drainage
High water table: No, no high water table anticipated in the area of review. Surface drainage leads to live water: No, nearest drainage is an unnamed ephemeral drainage a pothole lake, about 1/2 of a mile to the northeast from this location. Water well contamination: None, closest water wells are about 5/8 of a mile to the southeast and 3/4 of a mile to the southeast from this location. Depth of these domestic water wells are from 160' to 210'. Surface casing hole will be drilled with freshwater and freshwater drilling fluids. Surface casing will be run and cemented to surface from 2000'. Porous/permeable soils: No, sandy clay soils. Class I stream drainage: No class I stream drainages in this area. Mitigation: X Lined reserve pit X Adequate surface casing Berms/dykes, re-routed drainage Closed mud system
High water table: No, no high water table anticipated in the area of review. Surface drainage leads to live water: No, nearest drainage is an unnamed ephemeral drainage a pothole lake, about 1/2 of a mile to the northeast from this location. Water well contamination: None, closest water wells are about 5/8 of a mile to the southeast and 3/4 of a mile to the southeast from this location. Depth of these domestic water wells are from 160' to 210'. Surface casing hole will be drilled with freshwater and freshwater drilling fluids. Surface casing will be run and cemented to surface from 2000'. Porous/permeable soils: No, sandy clay soils. Class I stream drainage: No class I stream drainages in this area. Mitigation: X Lined reserve pit X Adequate surface casing Berms/dykes, re-routed drainage Closed mud system Off-site disposal of solids/liquids (in approved facility)
High water table: No, no high water table anticipated in the area of review. Surface drainage leads to live water: No, nearest drainage is an unnamed ephemeral drainage a pothole lake, about 1/2 of a mile to the northeast from this location. Water well contamination: None, closest water wells are about 5/8 of a mile to the southeast and 3/4 of a mile to the southeast from this location. Depth of these domestic water wells are from 160' to 210'. Surface casing hole will be drilled with freshwater and freshwater drilling fluids. Surface casing will be run and cemented to surface from 2000'. Porous/permeable soils: No, sandy clay soils. Class I stream drainage: No class I stream drainages in this area. Mitigation: X Lined reserve pit X Adequate surface casing Berms/dykes, re-routed drainage Closed mud system
High water table: _No, no high water table anticipated in the area of review Surface drainage leads to live water:No, nearest drainage is an unnamed ephemeral drainage a pothole lake, about 1/2 of a mile to the northeast from this location Water well contamination: _None, closest water wells are about 5/8 of a mile to the southeast and ¾ of a mile to the southeast from this location. Depth of these domestic water wells are from 160' to 210'. Surface casing hole will be drilled with freshwater and freshwater drilling fluids. Surface casing will be run and cemented to surface from 2000'. Porous/permeable soils: _No, sandy clay soils Class I stream drainage: _No class I stream drainages in this area

Soils/Vegetation/Land Use

(possible concerns)
Steam crossings: No, stream crossings anticipated.
High erosion potential: No, moderate cut, up to 10.5' and small fill, up to 6.3', required
Loss of soil productivity: None, location to be restored after drilling well, if well is
nonproductive. If productive unused portion of drillsite will be reclaimed.
Unusually large wellsite: No, a large wellsite 400'X440' location size required.
Damage to improvements: No surface use is a cultivated field.
Conflict with existing land use/values:Slight
Mitigation
Avoid improvements (topographic tolerance)
Exception location requested
X Stockpile topsoil
Stream Crossing Permit (other agency review)
X Reclaim unused part of wellsite if productive
Special construction methods to enhance reclamation
Other
Comments: Access to location will be over existing county road, FAS #405, (East
South Froid Road), CR 1010 and an existing two track section line road(Section line
road will be upgraded for heavy truck use). A short access of 90' will be built off the two
track road into location. Oil based invert drilling fluids will be recycled. Completion fluids
will be hauled to a Class II Disposal. Drilling cuttings and mud solids will be fly ashed in
the lined pit and buried with subsoil cover. No special concerns.
Health Hazards/Noise
(possible concerns)
Proximity to public facilities/residences: No residences within a 1 mile radius from this
location. The town of Froid, Montana is about 10.25 miles to the west northwest from
this location.
Possibility of H2S: H2S potential is slight
Size of rig/length of drilling time: Triple drilling rig/short 30 to 40 days drilling time.
Mitigation:
_X_Proper BOP equipment
Topographic sound barriers
H2S contingency and/or evacuation plan
H2S contingency and/or evacuation planSpecial equipment/procedures requirements
H2S contingency and/or evacuation planSpecial equipment/procedures requirementsOther:
 H2S contingency and/or evacuation plan Special equipment/procedures requirements Other: Comments: Adequate surface casing and operational BOP should mitigate any
H2S contingency and/or evacuation planSpecial equipment/procedures requirementsOther:
H2S contingency and/or evacuation plan Special equipment/procedures requirements Other: Comments: Adequate surface casing and operational BOP should mitigate any problems. No concerns
H2S contingency and/or evacuation plan Special equipment/procedures requirements Other: Comments: Adequate surface casing and operational BOP should mitigate any problems. No concerns. Wildlife/recreation
H2S contingency and/or evacuation plan Special equipment/procedures requirements Other: Comments: Adequate surface casing and operational BOP should mitigate any problems. No concerns. Wildlife/recreation (possible concerns)
H2S contingency and/or evacuation plan Special equipment/procedures requirements Other: Comments: Adequate surface casing and operational BOP should mitigate any problems. No concerns. Wildlife/recreation (possible concerns) Proximity to sensitive wildlife areas (DFWP identified): Medicine Lake National Wildlife
H2S contingency and/or evacuation plan Special equipment/procedures requirements Other: Comments: Adequate surface casing and operational BOP should mitigate any problems. No concerns. Wildlife/recreation (possible concerns) Proximity to sensitive wildlife areas (DFWP identified): Medicine Lake National Wildlife Refuge boundary is about 8.4 miles to the northwest from this location
H2S contingency and/or evacuation plan Special equipment/procedures requirements Other: Comments: Adequate surface casing and operational BOP should mitigate any problems. No concerns. Wildlife/recreation (possible concerns) Proximity to sensitive wildlife areas (DFWP identified): Medicine Lake National Wildlife Refuge boundary is about 8.4 miles to the northwest from this location. Proximity to recreation sites:Medicine Lake National Wildlife Refuge is about 8.4
H2S contingency and/or evacuation plan Special equipment/procedures requirements Other: Comments: Adequate surface casing and operational BOP should mitigate any problems. No concerns. Wildlife/recreation (possible concerns) Proximity to sensitive wildlife areas (DFWP identified): Medicine Lake National Wildlife Refuge boundary is about 8.4 miles to the northwest from this location.

Conflict with game range/refuge management: No Threatened or endangered Species: Species identified as threatened or endangered are the Pallid Sturgeon, Interior Lease Tern, Whooping Crane and Piping Plover. Candidate species is the Sprague's Pipit. MTFWP Natural Heritage Tracker website lists two (2) species of concerns. They are Baird's Sparrow and the Whooping Crane. Mitigation: Avoidance (topographic tolerance/exception) Other agency review (DFWP, federal agencies, DSL) Screening/fencing of pits, drillsite Other: Comments: The drilling of this well should have no effect on the Medicine Lake National Wildlife Refuge. The surface ownership is private land and surface use is cultivated surface lands. There may be species of concern that maybe impacted by this wellsite. We ask the operator to consult with the surface owner as to what he would like
done, if a species of concern is discovered at this location. The Board of Oil & Gas has
no jurisdiction over private surface lands.
Historical/Cultural/Paleontological
(possible concerns) Proximity to known sites None identified. Mitigation avoidance (topographic tolerance, location exception) other agency review (SHPO, DSL, federal agencies) Other: Comments: On private cultivated surface lands. There may be possible historical/cultural/paleontological sites that maybe impacted by this wellsite. We ask the operator to consult with the surface owner as to his desires to preserve these sites or not, if they are found during construction of the wellsite. The Board of Oil & Gas has no jurisdiction over private surface lands.
Social/Economic (possible concerns) Substantial effect on tax base Create demand for new governmental services Population increase or relocation Comments: No concerns.
Remarks or Special Concerns for this site
_19,548'MD/10,168'TVD Three Forks Formation horizontal well test. No concerns.

Summary: Evaluation of Impacts and Cumulative effects

No significant long term impacts expected, some short term impacts will occur.

I conclude that the approval of the subject Notice of Intent to Drill (does/ <u>does not</u>) constitute a major action of state government significantly affecting the quality of the human environment, and (does/ <u>does not</u>) require the preparation of an environmental impact statement.
Prepared by (BOGC):_\s\ Steven Sasaki
(title:) Chief Field Inspector
Date: January 29, 2012
Other Persons Contacted:
Montana Bureau of Mines and Geology, GWIC website
(Name and Agency)
Water wells in Roosevelt County
(subject discussed)
<u>January 29, 2012</u>
(date)
US Fish and Wildlife, Region 6 website
(Name and Agency)
ENDANGERED, THREATENED, PROPOSED AND CANDIDATE SPECIES
MONTANA COUNTIES, Roosevelt County
(subject discussed)
January 29, 2012
(date)
Montana Natural Heritage Program Website (FWP)
(Name and Agency)
Heritage State Rank= S1, S2, S3, T29N R57E
(subject discussed)
_January 29, 2012
(date)
If location was inspected before permit approval:
Inspection date:
Inspector:
Others present during inspection: